

TOPIC

Materials – Section IX – Question 13

QUESTION

Engineering normal stress is

- (A) always higher than the true stress
- (B) always lower than the true stress
- (C) the same as the true stress in all deformation regimes
- (D) all of the above

HINT

True stress takes into account the sample apparent cross-sectional area during loading.

CONTRIBUTOR

Alex Volinsky