

TOPIC

Materials – Section IX – Question 9

QUESTION

Eutectic reaction

- (A) happens only between the solid phases
- (B) causes an alloy to melt at temperatures lower than individual alloy components melting temperature
- (C) happens only between metals
- (D) is exothermic

HINT

Eutectic reaction is invariant.

CONTRIBUTOR

Alex Volinsky