

TOPIC

Materials – Section IX – Question 5

QUESTION

When plastically deformed, strain hardening causes metals to become

- (A) softer
- (B) harder
- (C) transparent
- (D) smoother

CONTRIBUTOR

Alex Volinsky