

TOPIC

Materials – Section IX – Question 11

QUESTION

In general and in most materials, crystallization causes

- (A) reduction of volume
- (B) cold fusion
- (C) light emission
- (D) all of the above

CONTRIBUTOR

Alex Volinsky